

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**IX1255**  
**East**  
**> 1**  
**1.626 mi.**  
**8586 ft.**

**BELT PKWY E B AT OCEAN AV**  
**BELT PARKWAY**  
**BROOKLYN, NY**

**NY Spills** **S102143074**  
**N/A**

**Site 1 of 2 in cluster IX**

**Relative:**  
**Higher**

**Actual:**  
**17 ft.**

**SPILLS:**

Name: BELT PKWY E B AT OCEAN AV  
Address: BELT PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9203960 / 1992-07-06  
Facility ID: 9203960  
Facility Type: ER  
DER Facility ID: 195583  
Site ID: 314996  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: B4  
SWIS: 2401  
Spill Date: 1992-07-06  
Investigator: KSTANG  
Referred To: Not reported  
Reported to Dept: 1992-07-06  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial Vehicle  
Spill Notifier: Fire Department  
Cleanup Ceased: 1992-07-06  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1992-07-07  
Spill Record Last Update: 2004-09-30  
Spiller Name: Not reported  
Spiller Company: Not reported  
Spiller Address: Not reported  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was TANG "  
Remarks: "NYCFD HAZ MAT CONFIRMED RECOVERY & CLEANUP."

**All Materials:**

Site ID: 314996  
Operable Unit ID: 971353  
Operable Unit: 01  
Material ID: 411728  
Material Code: 0008  
Material Name: diesel  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 100.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported